PRINTED: 09/29/2016
FORM APPROVED

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING	(X3) DATE SURVEY COMPLETED
	TN3317		09/26/2016

NAME OF PROVIDER OR SUPPLIER: LIFE CARE CENTER OF OOLTEWAH

STREET ADDRESS, CITY, STATE, ZIP CODE: 5911 SNOW HILL ROAD, OOLTEWAH, TN 37363

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 843	1200-8-6-.08 (13) Building Standards (13) Electrical drawings shall include where applicable: (a) A seal, certifying that all electrical work and equipment is in compliance with all applicable codes and that all materials are currently listed by recognized testing laboratories; (b) All electrical wiring, outlets, riser diagrams, switches, special electrical connections, electrical service entrance with service switches, service feeders and characteristics of the light and power current, and transformers when located within the building; (c) An electrical system that complies with applicable codes; (d) Color coding to show all items on emergency power; (e) Circuit breakers that are properly labeled; and (f) Ground-Fault Circuit Interrupters (GFCI) that are required in all wet areas, such as kitchens, laundries, janitor closets, bath and toilet rooms, etc, and within six (6) feet of any lavatory. This Rule is not met as evidenced by: Based on observation and testing, the facility failed to install Ground-Fault Circuit Interrupters in all wet areas. The findings include:	N 843	1) What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice. The Maintenance Director installed a Ground-Fault Circuit Interrupter behind the two washing machines in laundry and one in therapy on 10/10/16 2) How will you identify other residents having the potential to be affected by the same deficient practice and what corrective actions(s) will be taken. The Maintenance Director reviewed all electrical receptacles located in the facility in wet areas to ensure they are Ground-Fault Circuit Interrupter receptacles on 10/14/16. 3) What measures will be put into place or what systematic changes you will make to ensure that the deficient practice does not recur. The Maintenance Director or designee will review Ground-Fault Circuit Interrupter receptacles near wet areas for proper working order monthly.	10/28/16 10/28/16 10/28/16

Division of Health Care Facilities
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE: Diana Schlenz
TITLE: Executive Director
(X6) DATE: 10/20/16

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING:	(X3) DATE SURVEY COMPLETED
	TN3317		09/28/2016

NAME OF PROVIDER OR SUPPLIER: LIFE CARE CENTER OF OOLTEWAH

STREET ADDRESS, CITY, STATE, ZIP CODE: 5911 SNOW HILL ROAD, OOLTEWAH, TN 37363

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 843	1200-8-6-.06 (13) Building Standards (13) Electrical drawings shall include where applicable: (a) A seal, certifying that all electrical work and equipment is in compliance with all applicable codes and that all materials are currently listed by recognized testing laboratories; (b) All electrical wiring, outlets, riser diagrams, switches, special electrical connections, electrical service entrance with service switches, service feeders and characteristics of the light and power current, and transformers when located within the building; (c) An electrical system that complies with applicable codes; (d) Color coding to show all items on emergency power; (e) Circuit breakers that are properly labeled; and (f) Ground-Fault Circuit Interrupters (GFCI) that are required in all wet areas, such as kitchens, laundries, janitor closets, bath and toilet rooms, etc, and within six (6) feet of any lavatory. This Rule is not met as evidenced by: Based on observation and testing, the facility failed to install Ground-Fault Circuit Interrupters in all wet areas. The findings include:	N 843	N843 Continued 4) How the corrective action(s) will be monitored to ensure the deficient practice does not recur. The Maintenance Director will present the findings of the monthly Ground-Fault Circuit Interrupter Review to the facility Performance Improvement (PI) Committee. This committee consisting of the Executive Director, Director of Nursing, Medical Director, Director of Maintenance, Director of Rehab, Health Information Management Director, Director of Food and Nutrition Services, Director of Environmental Services, Director of Social Services, Business Office Manager, Director of Admissions, and Director of Activities will review the findings and make recommendations and develop plans of action if any areas are noted to be non-compliant. This will occur monthly.	10/28/16

Division of Health Care Facilities
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE: Thomas Schlaum
TITLE: Executive Director
(X6) DATE: 10/20/16

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	TN3317	A. BUILDING: 01 - MAIN B. WING	09/26/2016

NAME OF PROVIDER OR SUPPLIER: LIFE CARE CENTER OF COLTEWAH

STREET ADDRESS, CITY, STATE, ZIP CODE: 5911 SNOW HILL ROAD, COLTEWAH, TN 37363

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 843	1200-8-6-.08 (13) Building Standards (13) Electrical drawings shall include where applicable: (a) A seal, certifying that all electrical work and equipment is in compliance with all applicable codes and that all materials are currently listed by recognized testing laboratories; (b) All electrical wiring, outlets, riser diagrams, switches, special electrical connections, electrical service entrance with service switches, service feeders and characteristics of the light and power current, and transformers when located within the building; (c) An electrical system that complies with applicable codes; (d) Color coding to show all items on emergency power; (e) Circuit breakers that are properly labeled; and (f) Ground-Fault Circuit Interrupters (GFCI) that are required in all wet areas, such as kitchens, laundries, janitor closets, bath and toilet rooms, etc, and within six (6) feet of any lavatory. This Rule is not met as evidenced by: Based on observation and testing, the facility failed to install Ground-Fault Circuit Interrupters in all wet areas. The findings include:	N 843		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE: Diana Schlenz

TITLE: Executive Director

(X6) DATE: 10/20/16

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING	(X3) DATE SURVEY COMPLETED
	TN3317		09/26/2016

NAME OF PROVIDER OR SUPPLIER: LIFE CARE CENTER OF OOLTEWAH

STREET ADDRESS, CITY, STATE, ZIP CODE: 5911 SNOW HILL ROAD, OOLTEWAH, TN 37363

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 843	Continued From page 1 Observation with the maintenance director, on 9/26/16 between 1:50 PM and 3:00 PM revealed Ground-Fault Circuit Interrupters were not installed behind the two washing machines in laundry and one on therapy. These findings were verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/26/16.	N 843		

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING	(X3) DATE SURVEY COMPLETED
	TN3317		09/26/2016

NAME OF PROVIDER OR SUPPLIER: LIFE CARE CENTER OF OOLTEWAH

STREET ADDRESS, CITY, STATE, ZIP CODE: 5911 SNOW HILL ROAD, OOLTEWAH, TN 37363

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 843	Continued From page 1 Observation with the maintenance director, on 9/26/16 between 1:50 PM and 3:00 PM revealed Ground-Fault Circuit Interrupters were not installed behind the two washing machines in laundry and one on therapy. These findings were verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/26/16.	N 843		

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN B. WING	(X3) DATE SURVEY COMPLETED
	TN3317		09/26/2016

NAME OF PROVIDER OR SUPPLIER: LIFE CARE CENTER OF OOLTEWAH

STREET ADDRESS, CITY, STATE, ZIP CODE: 5911 SNOW HILL ROAD, OOLTEWAH, TN 37363

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 843	Continued From page 1 Observation with the maintenance director, on 9/26/16 between 1:50 PM and 3:00 PM revealed Ground-Fault Circuit Interrupters were not installed behind the two washing machines in laundry and one on therapy. These findings were verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/26/16.	N 843		