

## Post-Certification Revisit Report

Public reporting for this collection of information is estimated to average 10 minutes per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to CMS, Office of Financial Management, P.O. Box 26884, Baltimore, MD 21207; and to the Office of Management and Budget, Paperwork Reduction Project (0938-0390), Washington, D.C. 20503.

(Y1) Provider / Supplier / CLIA / Identification Number 445033	(Y2) Multiple Construction A. Building 03 - BIRMINGHAM B. Wing	(Y3) Date of Revisit 3/9/2009
Name of Facility BORDEAUX LONG TERM CARE	Street Address, City, State, Zip Code 1414 COUNTY HOSPITAL RD NASHVILLE, TN 37218	

This report is completed by a qualified State surveyor for the Medicare, Medicaid and/or Clinical Laboratory Improvement Amendments program, to show those deficiencies previously reported on the CMS-2567, Statement of Deficiencies and Plan of Correction that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the CMS-2567 (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item	(Y6) Date	(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date
ID Prefix _____ Reg. # NFPA 101 LSC K0025	Correction Completed 03/09/2009	ID Prefix _____ Reg. # NFPA 101 LSC K0039	Correction Completed 03/09/2009	ID Prefix _____ Reg. # NFPA 101 LSC K0052	Correction Completed 03/09/2009
ID Prefix _____ Reg. # NFPA 101 LSC K0067	Correction Completed 03/09/2009	ID Prefix _____ Reg. # NFPA 101 LSC K0147	Correction Completed 03/09/2009	ID Prefix _____ Reg. # NFPA 101 LSC K0211	Correction Completed 03/09/2009
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed

Reviewed By <input checked="" type="checkbox"/>	Reviewed By <i>DP</i>	Date: 3/9/09	Signature of Surveyor: <i>Jan Priddy</i>	Date: 3/9/09
Reviewed By _____	Reviewed By _____	Date: _____	Signature of Surveyor: _____	Date: _____

Followup to Survey Completed on: 2/2/2009	Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility? YES NO
--	--

Post-Certification Revisit Report

Public reporting for this collection of information is estimated to average 10 minutes per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to CMS, Office of Financial Management, P.O. Box 26664, Baltimore, MD 21207; and to the Office of Management and Budget, Paperwork Reduction Project (0938-0390), Washington, D.C. 20503.

(Y1) Provider / Supplier / CLIA / Identification Number 445033	(Y2) Multiple Construction A. Building 01 - RIBEIRO B. Wing	(Y3) Date of Revisit 3/9/2009
---	---	----------------------------------

Name of Facility BORDEAUX LONG TERM CARE	Street Address, City, State, Zip Code 1414 COUNTY HOSPITAL RD NASHVILLE, TN 37218
---	---

This report is completed by a qualified State surveyor for the Medicare, Medicaid and/or Clinical Laboratory Improvement Amendments program, to show those deficiencies previously reported on the CMS-2567, Statement of Deficiencies and Plan of Correction that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the CMS-2567 (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date
ID Prefix _____ Reg. # NFPA 101 LSC K0018	Correction Completed 03/09/2009	ID Prefix _____ Reg. # NFPA 101 LSC K0025	Correction Completed 03/09/2009	ID Prefix _____ Reg. # NFPA 101 LSC K0050	Correction Completed 03/09/2009
ID Prefix _____ Reg. # NFPA 101 LSC K0147	Correction Completed 03/09/2009	ID Prefix _____ Reg. # NFPA 101 LSC K0211	Correction Completed 03/09/2009	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed
ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed	ID Prefix _____ Reg. # _____ LSC _____	Correction Completed

Reviewed By <input checked="" type="checkbox"/>	Reviewed By <i>BP</i>	Date: 3/9/09	Signature of Surveyor: <i>Jan Priddy</i>	Date: 3/9/09
Reviewed By _____	Reviewed By _____	Date: _____	Signature of Surveyor: _____	Date: _____

Followup to Survey Completed on: 2/2/2009	Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility? YES NO
--	--